

Penetrant test report



Report number	LW26-0253-07 PT Rev. 1	(This report supersedes LW26-0253-07 PT)
Customer name	AAS STEEL PTY LTD	
Address	9 Trade Place Pakenham VIC Australia 3810	
Requested by	Shan Senn	
Purchase Order	01000824	
Accredited laboratory	LMATS Melbourne Laboratory	
Test date	06/03/2026	
Job address	13 Paramount Road West Footscray	
Job description	Visible dye penetrant testing on 350NB header weldments	
Identification	Job: VMM00120 NEXT DC M3 STAGE 2; Drawing: SDRG-B-0201-8241	
Material grade	Stainless Steel- Grade not specified	
Test specification	Client's requirement - Report findings	
Test method	AS ISO 3452.1:2021-PT - colour contrast	
Test designation	ISO 3452-2, IICeL2-Colour contrast (visible), solvent removal & developer, L2 sensitivity	
Test procedure	TP-PT-15 (I2, R1)	
Production Stage	After fabrication, in-situ	
Test area	Weld zone & associated HAZ (Refer Table 1 for identification)	
Test temperature	18°C to 21 °C approximate range	
Equipment	L004715 Light meter Hold Peak 881D	
Lighting conditions	White light illuminance >1200 lx	
Surface condition	As welded, blended intermittently	
Surface preparation	Solvent flushed and wiped. Natural evaporation.	
Chemicals details		
Precleaner	MR Chemie MR85	Batch No. 85/2005
Penetrant	MR Chemie MR311-R	221108
Developer	MR Chemie MR70I	70I/2003
Remover	Not Applicable	Not Applicable
Approved tester	Lachlan Hooppell (SNT-TC-1A and AINDT L2 - RT MT PT)	
Other testers	Mark Borg (AINDT L2 - MT ET / SNT-TC-1A L2 - RT MT & L1 UTT)	
Test results	Refer to Table 1 for test area identification and results	



Accreditation No. 15840

Accredited for compliance with
ISO / IEC 17025 - Testing

Signatory
Lachlan Hooppell
(SNT-TC-1A and AINDT L2 - RT MT PT)

Report issued on 11/03/2026

Report no. LW26-0253-07 PT Rev. 1, AAS STEEL PTY LTD, Page 1 of 6, Format no. OMS MF-RP-17 PT OMS(Rev. 5.0 20251011)

Table 1: Test items identification (provided by the client) and results (All dimensions in mm unless stated otherwise)

Identification	Spool No.	Weld No.	Description	Test area	Discontinuities
South end	Spool 4	1	Bottom header	7-5 o'clock Facing north	LS35 @ 12ocl, CC5 @ 2ocl, LS20 @ 4ocl, LS50 @ 6ocl, LS15 @ 7ocl, uniform porosity
South end	Spool 4	2	Bottom header	7-5 o'clock Facing east	LS30 @ 6ocl, LS25 @ 1ocl, LS15 @ 3ocl, uniform porosity
South end	Spool 4	3	Bottom header	7-5 o'clock Facing west	CC5 @ 10ocl, LS25 @ 10ocl, LS15 @ 12ocl, CC10 @ 3ocl, LS10 @ 3ocl, uniform porosity
South end	Spool 4	4	Bottom header	7-5 o'clock Facing east	CC10 @ 7ocl, LS10 @ 11ocl, LS30 @ 9ocl, LS25 @ 6ocl, uniform porosity
South end	Spool 4	5	Bottom header	7-5 o'clock Facing west	CC3 @ 12ocl, CC10 @ 12ocl, LS25 @ 12ocl, LS15 @ 3ocl, LS30 @ 5ocl, LS40 @ 8ocl, uniform porosity
South end	Spool 4	6	Bottom header	7-5 o'clock Facing south	Uniform porosity
South end	Spool 4	7	Bottom header	7-5 o'clock Facing east	CC10 @ 1ocl, LS10 @ 12ocl, GP1 @ 3ocl, GP1 @ 3ocl, LS40 @ 4ocl
South end	Spool 4	8	Bottom header	7-5 o'clock Facing west	LS60 @ 6ocl, LS50 @ 7ocl, LS15 @ 3ocl, LS20 @ 1ocl, LS35 @ 9ocl
South end	Spool 4	9	Bottom header	7-5 o'clock Facing east	LS15 @ 11ocl, LS20 @ 6ocl, CC15 @ 7ocl
South end	Spool 4	10	Bottom header	7-5 o'clock Facing west	CC5 @ 12ocl, CC5 @ 12ocl, LS30 @ 3ocl, LS80 @ 6ocl, LS60 @ 7ocl, LS20 @ 9ocl
South end	Spool 4	11	Bottom header	7-5 o'clock Facing south	LS20 @ 3ocl, uniform porosity
South end	Spool 4	1	Top header	6-12 o'clock Facing north	LS35 @ 9ocl, LS20 @ 8ocl, LS25 @ 7ocl, random blob of weld in PM @ position 7 possible hole repair
South end	Spool 4	2	Top header	Entire facing east	CC5 @ 1ocl, LS15 @ 9ocl, LS20 @ 8ocl, LS20 @ 6ocl, LS10 @ 7ocl
South end	Spool 4	3	Top header	Entire facing west	LS5 @ 11ocl, LS20 @ 3ocl
South end	Spool 4	4	Top header	Entire facing east	LS10 @ 2ocl, SSX15 @ 3ocl, LS15 @ 5ocl, LS15 @ 8ocl, LS20 @ 9ocl, LS20 @ 9ocl
South end	Spool 4	5	Top header	Entire facing west	LS25 @ 9ocl, LS20 @ 6ocl, LS15 @ 3ocl
South end	Spool 4	6	Top header	12-7 facing south	LS15 @ 12ocl, LS30 @ 3ocl, LS30 @ 5ocl, LS100 @ 6ocl, spatter

Identification	Spool No.	Weld No.	Description	Test area	Discontinuities
South end	Spool 4	7	Top header	NA	No access due to building edge
South end	Spool 4	8	Top header	NA	No access due to building edge
South end	Spool 4	9	Top header	NA	No access due to building edge
South end	Spool 4	10	Top header	NA	No access due to building edge
South end	Spool 4	11	Top header	NA	No access due to building edge

Test restrictions

Restricted access to 5-7 o'clock position of weld between header and grating, could not adequately apply dye and developer in these positions in-situ. Bolts at flanges also limiting access

Comments

Refer to attached images

Test, inspection process specific notes

- This test method cannot detect sub-surface discontinuities or surface opening discontinuities covered with coating.

Normative general notes

1. Test and inspection items may be discarded after 6 weeks, unless alternative arrangements are made with LMATS.
2. Samples, identification of samples and all job specific details were supplied by the client. The test results relate only to the items tested or sampled.
3. Any stated nominal pipe sizes and nominal thickness of the material were provided by the client.
4. Where applicable, the Measurement Uncertainty (MU) applies to the test results as per LMATS procedure. MU can be obtained by contacting one of LMATS ISO 17025 accredited laboratories.
5. Acceptance criteria is applied from the test specification. If the test specification does not include acceptance criteria, then the test or inspection results should be referred to a competent authority for further action.
6. Refer to the attached revision notes if this report has been revised. This report shall not be reproduced except in full without approval of the issuing laboratory to ensure that parts of a report are not taken out of context. The client or their representatives shall not edit this report.
7. LMATS or its professional indemnity insurance provider do not indemnify the contents within this report or the conformity of a tested product unless the invoice for the reported work is paid in full within the agreed credit terms. Reports will be revoked if the invoice for the completed work is not paid in full.

Abbreviations used in this report

A - No discontinuities detected

CP - Crater Pipe

F - Failed

IC - Copper Inclusion

IO - Oxide Inclusion (wagon tracks)

KL - Longitudinal crack

LP - Incomplete root Penetration

NRRD - No Recordable Reflections Detected

p.d. - Processing / film Defects

PU - Uniform Porosity

SGI - Incompletely filled Groove

SMH - Hammer Mark

SSP - Spatter

SXP - Excessive Penetration

BT - Burn (melt) Through

DNC - Does Not Comply

GP - Gas Pore

IL - Linear Inclusion (slag line)

IT - Tungsten Inclusion

KT - Transverse crack

LR - lack of Root fusion (missed edge)

NUSID - No unacceptable Surface Indications Detected

PG - Localized Porosity

RP - Report findings

SGS - Shrinkage Groove

SMT - Tool Mark (chipping mark)

SUC(e) - Undercut External

WH - Worm Hole

C - Comply

EC - Elongated Cavity (hollow bead)

HiLo - Linear misalignment

IN - Inclusion

KC - Crater crack

LI - lack of Inter-run fusion

LS - lack of Side fusion

P - Passed

PL - Linear Porosity

SED - Excessive Dressing (underflushing)

SMG - Grinding Mark

SRC - Root Concavity (Suck back)

SUC(i) - Undercut Internal



Image 1 of 6 - Bottom header South end spool #4 W9-11



Image 2 of 6 - Bottom header South end spool #4 W7-8




Image 3 of 6 - Bottom header South end spool #4 W6




Image 4 of 6 - Bottom header South end spool #4 W1-5




Image 5 of 6 - Top header South end spool #4 W6



Image 6 of 6 - Top header South end spool #4 W1-5

REVOKED



MATERIAL LIST

CODE:	QTY:	SIZE:	DESCRIPTION OR CUTTING LENGTH:	END TREAT:
A	5	Ø350	TABLE 'E' FLANGE	
B	17	Ø250	TABLE 'E' FLANGE	

PIPE SPEC: STAINLESS STEEL GRADE 304 SCHEDULE 10

SYMBOL ABBREVIATIONS

WELDER	DATE
MATERIAL AS LISTED	
DIMENSIONS CHECKED	
CHECK FOR SQUARE	
CHECK CONFIGURATION	
IDENTIFICATION CHECK	
MATERIALS ORDERED BY	☐ SITE
	☐ WORKSHOP

DATE REQUIRED



talented people...
sustainable solutions

D&E Air Conditioning Pty Ltd

www.de-air.com.au
E: drafting@de-air.com.au
ABN: 24 158 631 979

ACN: 158 631 979
ARC: #AU29715

Melbourne (Head Office)
11 Corporate Avenue
Rowville, VIC 3178
T: +61 3 9751 4222

Sydney
Level 5
113 Wicks Road
Macquarie Park, NSW 2113
T: +61 2 8047 4610

Adelaide
85 Ormond Street
Hindmarsh, SA 5007
T: +61 8 7969 6677

Perth
23 Wheeler Street
Belmont, WA 6104
T: +61 8 6247 5970

Geelong
36-39 Industrial Place
Breakwater, VIC 3219
T: +61 3 5229 2200

Brisbane
16 Container Street
Tingalpa, QLD 4173
T: +61 7 3175 4999

JOB: VMM00120 NEXT DC M3 STAGE 2

DATE: 08.09.25	REF.DRG.NO: SDRG-B-0201-8241
DRAWN: T.MOSER	SKETCH NO: URF-B1-M-CCW-001 FC-1

Normative revision notes for Report No. LW26-0253-07 PT Rev. 1

Result table Row No.: 12, Col.: Test area revised from "5-12 o'clock Facing north" to "6-12 o'clock Facing north"

Result table Row No.: 17, Col.: Test area revised from "Entire facing south" to "12-7 facing south"

Result table Row No.: 18, Col.: Test area revised from "Entire facing east" to "NA"

Result table Row No.: 19, Col.: Test area revised from "Entire facing west" to "NA"

Result table Row No.: 20, Col.: Test area revised from "Entire facing east" to "NA"

Result table Row No.: 21, Col.: Test area revised from "Entire facing west" to "NA"

Result table Row No.: 22, Col.: Description revised from "1Top header" to "Top header"

Result table Row No.: 22, Col.: Test area revised from "Entire facing south" to "NA"

Report No. revised from "LW26-0253-07 PT" to "LW26-0253-07 PT Rev. 1"

REVOKED